

Figure 14-10. Generic T/C Thermometers and Various Reference-Junction Techniques.